

BroadSound Reparable Ultrasound Transducer List

07-Nov-2024

Item	Make	Model	Compatible System	Note	Item	Make	Model	Compatible System	Note
1	Acuson	4C1	SEQUOIA	***	71	Philips	C5-2 [21426A]	Envisor, HD11(XE), HD7	***
2	Acuson	6L3	SEQUOIA		72	Philips	CA5-2 [21425A]	Envisor, HD11(XE), HD7	***
3	Acuson	8L5	SEQUOIA		73	Philips	C8-4V [21437A]	Envisor, HD11(XE), HD7	***
4	Acuson	15L8W	SEQUOIA	***	74	Philips	L12-3 [21475A]	Envisor, HD11(XE), HD7	***
5	Acuson	4C1	Cypress/Cypress Plus	***	75	Philips	C5-2	HD3	
6	Acuson	6C2	SEQUOIA 512	***	76	Philips	C7-3	HD3	
7	Acuson	6C1 HD	S2000/ S3000	***	77	Philips	C9-4	HD3	
8	Siemens	CH5-2	G40	***	78	Philips	C9-4ec	HD3	
9	Siemens	VF10-5 [08648110]	G40	***	79	Philips	L9-5	HD3	***
10	Siemens	P4-2	G40/X150/X300/X300PE		80	Philips	C8-5	Envisor	
11	Siemens	P8-4	G40/X150/X300/X300PE		81	Philips	L12-3	CX50 Compact Xtreme/ HD5	***
12	Siemens	C5-2	Sienna/G50		82	Philips	L12-5 (50 mm)	CX 50	***
13	Siemens	C6-2	CV70/G60s/X300PE/X500		83	Philips	C5-1	CX50	***
14	Siemens	C8-5	X300/X300PE		84	Philips	S5-1	CX50	***
15	Siemens	L10-5	G50/G60		85	Philips	C8-5	CX50	
16	Siemens	VF13-5 [10030614]	G50/G60		86	Philips	C6-2	Sparq	***
17	Siemens	EC9-4	Acuson X500/Sonoline G60s		87	Philips	L12-3 Ergo	Affiniti 50, Epiq 76	***
18	Siemens	C5-2	Antares		88	Philips	L12-4	Affiniti 50/ 70	
19	Siemens	CH4-1	Antares	***	89	GE	3S	Logiq 5/7/P5	***
20	Siemens	CH6-2	Antares	***	90	GE	5S	Logiq P5	
21	Siemens	VF7-3 [04839507]	Antares	***	91	GE	7S	Logiq 7/P5	
22	Siemens	VF10-5	Antares	***	92	GE	3.5C	Logiq 5/7/9/P5	
23	Siemens	VF13-5	Antares		93	GE	3.5CS [2051858]	Logiq 5/P5	
24	Siemens	EC9-4	Antares		94	GE	3C	Logiq 5/7	
25	Siemens	VF12-4	Acuson NX3, X600/ X700	***	95	GE	4C	Logiq P5	***
26	Siemens	VF13-5 [10789372]	ACUSON P500		96	GE	5C	Logiq 5/7	
27	Aloka	UST-934N-3.5	SSD 500		97	GE	8C	Logiq A5/P3/P5 /P6/P6pro/S6, Vivid 7	
28	Aloka	UST-981-5.0	SSD 500		98	GE	E8C	Logiq 5/7/9/P5	***
29	Aloka	UST-5512U-7.5	SSD 500		99	GE	7L [2302648]	Logiq 7/9	
30	Aloka	UST-979-3.5	SSD 900	***	100	GE	8L	Logiq P5	***
31	Aloka	UST-984-5	SSD 900		101	GE	9L	Logiq 7/ 9/ P5/ P6	***
32	Aloka	UST-987-7.5	SSD 900		102	GE	11L	Logiq P5	
33	Aloka	UST-990-5	SSD 900	***	103	GE	10L	Logiq 3 Exp/5/7/9 & Vivid 3/5/7	
34	Aloka	UST-9104-5	SSD 900		104	GE	12L	Logiq 5	
35	Aloka	UST-9112-5.0	SSD 900		105	GE	4C-RC	Logiq c2/ c3/ c5/ premium	
36	Aloka	UST-5524-7.5	SSD 900		106	GE	7.5L-RC	Logiq c2/ c3/ c5/ c5 premium	
37	Aloka	UST-5710-7.5	Prosound Alpha 5/ 6		107	GE	3S-RS	Logiq Book	***
38	Aloka	UST-5299	SSD 3500/4000		108	GE	3C-RS	Logiq Book	
39	Aloka	UST-5542	SSD 3500/4000		109	GE	4C-RS	Logiq Book	***
40	Aloka	UST-5546	SSD 3500/4000		110	GE	8C-RS	Logiq F3/F5/F6/F8, Voluson S6/S8	
41	Aloka	UST-9123	SSD 3500/4000	***	111	GE	E8C-RS	Logiq Book	***
42	Aloka	UST-9124	SSD 3500/ 4000/ Alpha 6		112	GE	8L-RS	Logiq Book	***
43	Aloka	UST-5548	SSD 3500/Alpha 5SX/7/10		113	GE	10Lb-RS	Logiq Book	
44	Aloka	UST-5539-7.5	SSD 5000/5500		114	GE	7S-RS	Vivid S6, Vivid I	
45	Aloka	UST-5545	SSD 5000/5500		115	GE	4C-A	VOLUSON 730	***
46	Aloka	UST-9114-3.5	SSD 5000/5500	***	116	GE	AC2-5	VOLUSON 730	
47	Aloka	UST-9119	SSD 5000/5500	***	117	GE	AB2-5	VOLUSON 730	
48	Aloka	UST-9126	Alpha 5SX	***	118	GE	AB2-7	VOLUSON 730	
49	Aloka	UST-5410	Alpha 5		119	GE	SP4-10	VOLUSON 730	
50	Aloka	UST-52101N	Alpha 5		120	GE	SP6-12	VOLUSON 730	
51	Aloka	UST-5543	Alpha 5/10		121	GE	SP10-16	VOLUSON 730	
52	Aloka	UST-9115-5	Alpha 5/7/10	***	122	GE	PA2-5	VOLUSON 730	
53	Aloka	UST-52105	Alpha 7/10		123	GE	IC5-9	VOLUSON 730	
54	Aloka	UST-5412	Alpha 7/10		124	GE	IC5-9H	VOLUSON 730	
55	Aloka	UST-9130	Alpha 10	***	125	GE	4C-D	VOLUSON E8	***
56	Aloka	UST-9137	ProSound 2	***	126	GE	SP10-16-D	VOLUSON E8	
57	Aloka	UST-9147	Prosound F75	***	127	GE	9L-D	Vivid E9, Logiq E9/ S8, Voluson E8 Expert	***
58	Aloka	UST-9118	Prosound Alpha 5/ 7/ 10, Prosound F75		128	GE	11L-D	Logiq E9, Vivid e9	
59	Aloka	UST-9127	SSD 3500/ 4000	***	129	GE	C1-5-D	logiq e9/voluson e6/ e8	***
60	Aloka	UST-5413	ProSound 3500SX/ Alpha 6/ F37	***	130	GE	C1-6-D	Vivid S60/ S70/ E90/ E95, Logiq E9/ S7	***
61	Aloka	UST-567	Alpha 5/ 5SX/ 7/ 10, ProSound F75		131	GE	AB2-7-D	Voluson E8	
62	Aloka	UST-568	Alpha 5/ 7/ 10, SSD 900/ 3500		132	GE	IC5-9-D	Vivid E95/S60N/S70N, Voluson E8/E10	
63	Philips	L9-3	IU22/IE33	***	133	GE	5CS	Logiq P3, Logiq P5, Logiq P5 Premium	***
64	Philips	L12-5 (50mm)	IU22	***	134	GE	E8CS	Logiq A5/ P3/ P5/ P6	
65	Philips	C5-1	IU22/ iE33 / HD11 XE	***	135	GE	3Sc-RS	Vivid S60/ T8/ S5/ iq, LOGIQ P9/ e	***
66	Philips	C5-2	IU22	***	136	GE	12L-RS	Logiq I, Vivid S5/ S6, Voluson e/ I	***
67	Philips	S5-1	IU22/ iE33	***	137	GE	AB2-7-RS	Voluson I, Voluson S6, Voluson S8	
68	Philips	S5-2	HD15	***	138	GE	C1-5-RS	Voluson S6/ S8/ S10, LOGIQ P9/ e	***
69	Philips	C6-3	HD11	***	139	GE	L6-12-RS	Logiq V1/V2/V3/V5/V5 Expert/P7/P9/P10	***
70	Philips	C8-5	HD11/11XE, IU22, IE33		140	Hitachi	EUP-C314	EUB-405+	

BroadSound Repairable Ultrasound Transducer List

07-Nov-2024

Item	Make	Model	Compatible System	Note	Item	Make	Model	Compatible System	Note
141	Hitachi	EUP-C314T	EUB-405+		195	Esaote	LA435	MyLab 15/20/70	***
142	Hitachi	EUP-C314G	EUB-405+		196	Esaote	LA522E	Megas/MyLab 15/25/30/40/70	***
143	Hitachi	EUP-C514	EUB-405+		197	Esaote	LA523	MyLab 15/25/30/40/50/70	***
144	Hitachi	EUP-L34T	Hi-Vision 5500/6500		198	Esaote	LA523E	MyLab 15/25/30/40/50/70	***
145	Hitachi	EUP-L33ST	EUB-405+/420/525/555		199	Esaote	CA123	MyLab 15/25/30/50/70	
146	Hitachi	EUP-L53S	EUB-405+/500/525/2000/5500/6500/8500		200	Esaote	CA621	MyLab 15/25/30/50/70	***
147	Hitachi	EUP-L65	EUB-5500/8500		201	Esaote	CA631	MyLab 15/25/30/40/50/70	***
148	Hitachi	EUP-L54M	EUB-405+/500/525/2000/5500/6500/8500		202	Esaote	CA421	MyLab 25/30	
149	Hitachi	EUP-L54MA	EUB-5500		203	Esaote	CA431	MyLab 50/70	
150	Hitachi	EUP-C715	EUB-405/500/525/2000/5500/6500/8500	***	204	Esaote	PA230E	MyLab 25	
151	Hitachi	C251	Arietta 70	***	205	Esaote	PA220E	Megas, Caris Plus	
152	Hitachi	EUP-L75	Hi Vision Avius		206	Esaote	CA11	AU3 / AU4 / AU5 / Megas / Caris	
153	Fujifilm	C253	Arietta 850 SE/ 750/ 65/ 50 LE	***	207	Esaote	EC123	MyLab 40/ 40CV/ 50/ 50XV/ 70XV/Gold	
154	Toshiba	PVG-366M	SSA 220A		208	Esaote	PA240	MyLab Twice	
155	Toshiba	PVE-375M	SSA 240A		209	Esaote	PA122E	MyLab 30Gold/ 40/ 50Vision/ 70Vision	
156	Toshiba	PVF-375MT	SSA 340A		210	Esaote	SC3123	MyLab one	
157	Toshiba	PVF-375AT	SSA 340A		211	Esaote	SL3323	MyLab one	
158	Toshiba	PVF-621VT	SSA 340A		212	Esaote	CA1421	MyLab 15/20/30	
159	Toshiba	PLF-703NT	SSA 340A		213	SonoSite	C60/5-2	Sono Site 180 plus	***
160	Toshiba	PLF-805ST	SSA 340A		214	SonoSite	L38/10-5	Sonosite 180 Plus / Titan	***
161	Toshiba	PVF-745V	SSA 370A/ 530A/ 550A/ 580A/ 590A		215	SonoSite	L38e/10-5	Sonosite Micromaxx	***
162	Toshiba	PVM-375AT	SSA-370A/SSA-550A/SSA-580A		216	SonoSite	HFL38/13-6	Sonosite Micromaxx	
163	Toshiba	PVM-621VT	SSA-370A/SSA-550A		217	SonoSite	HFL38x/13-6	Sonosite M-Turbo system	
164	Toshiba	PVM-651VT	SSA-370A/SSA-550A/SSA-580A		218	SonoSite	C60e/5-2	Sonosite Micromaxx	
165	Toshiba	PLM-703AT	SSA-370A/SSA-550A/SSA-580A		219	Honda	HCS-436S	HS 2000	
166	Toshiba	PLM-805AT	SSA-370A/SSA-550A/SSA-580A		220	Honda	HCS-436M	HS 2000/2500/4000	
167	Toshiba	PLM-1204AT	SSA 370A		221	Honda	HLS-413	HS-2000/ HS-2500/ HS-4000	
168	Toshiba	PLM-1204AT	SSA 370A		222	Sonoscape	L741	SSI 1000/3000/5000/6000	
169	Toshiba	PST-25AT	SSA 700A/SSA 770A		223	Sonoscape	C344	SSI 1000/2000BW/4000/5000/6000	
170	Toshiba	PST-30BT	SSA 700A/SSA 770A		224	Sonoscape	6V1	SSI 1000/3000/5000/6000	
171	Toshiba	PVT-375AT	SSA-660A/ SSA 700A/ SSA 770A	***	225	BK	8820	Pro Focus 2202	***
172	Toshiba	PVT-375BT	SSA-660A/ SSA 700A/ SSA 770A	***	226	BK	8820e	Pro Focus 2202/ Flex Focus 1202	***
173	Toshiba	PVT-661VT	SSA-660A/ SSA 700A/ SSA 770A	***	227	BK	6C2	bk3000, bk3500, bk5000	***
174	Toshiba	PLT-604AT	SSA-660A/ SSA 700A/ SSA 770A	***	228	Mindray	3C5A	DC-6/ DC-7	***
175	Toshiba	PLT-704AT	SSA-660A/ SSA 700A/ SSA 770A	***	229	Mindray	65EC10HA	Dp9900	
176	Toshiba	PLT-805AT	SSA-660A/ SSA 700A/ SSA 770A	***	230	Mindray	7L4A	DC-6	
177	Toshiba	PLT-1204AT	SSA-660A/ SSA 700A/ SSA 770A	***	231	Mindray	C5-2	DC-7	
178	Toshiba	PLT-704SBT	SSA 790A	***	232	Mindray	C5-2s	M5, M5 Vet, M7, M7 Vet, TE7, TE7 Vet	***
179	Toshiba	PLT-1005BT	Aplio 300/ 400/ 500	***	233	SIUI	C3L60C	Apogee 3500	
180	Toshiba	PLT-1204BT	Aplio/ Xario	***	234	Kontron	2-5CA	Imagic Elite, Sigma 5000	
181	Toshiba	PVT-781VT	Aplio 300/ 400/ 500/ i700/ i800/ i900		235	Kontron	5-12L50	Sigma 5000	
182	Toshiba	PVT-375ST	Viamo	***	236	Terason	12L5-V	Terason t3000	
183	Toshiba	PLT-704ST	Viamo	***	237	Terason	15L4	Terason t3200/usmart 3200T/3300	
184	Toshiba	PVU-375BT	Xario 100/ 200	***	238	Ultrasonix	L14-5/38	SonixSP / SonixOP / SonixTablet	
185	Toshiba	PVU-382BT	Xario 100/ 200	***	239	Konica	C5-2	Sonimage HS1	***
186	Toshiba	PLU-704BT	Xario 100/ 200	***	240	Konica	L11-3	Sonimage HS1	***
187	Toshiba	PLU-1005BT	Xario 100/ 200	***	241	Konica	L18-4	Sonimage HS1	
188	Toshiba	PLU-1204BT	Xario 100/ 200	***	242	SuperSonic Imagine	SC6-1	Aixplorer	
189	Fukuda	FUT-C111A	UF-4000						
190	Fukuda	FUT-C111	UF-4100		243	SuperSonic Imagine	SL15-4	Aixplorer	***
191	Fukuda	FUT-CS602-5AJ	UF-4100						
192	Fukuda	FUT-LS386-9A	UF-4100						
193	Fukuda	FUT-CA602-5P	UF-760AG	***					
194	Fukuda	FUT-LA385-12P	UF-760AG						

- The above-listed ultrasound transducer assemblies can be repaired by replacing with new acoustic module, replacing with new scan-head, or fixing embedded electronic PCBs if necessary.
- As to those other models not listed above, we need to physically check the defective transducer itself to determine whether we have relevant components to economically repair it.
- During repair, we'll do our best to keep the original scan-head plastic housing intact and reuse it; however, in case the original scan-head plastic housing cracked or was damaged, then we'll suggest to use our in-house new scan-head housing.
- The shape / appearance of our in-house scan-head housing would be different from that of OEM probe; therefore, the biopsy guide device for the OEM probe, if it existed, may not fit on our in-house scan-head after repair.
- Limited Warranty for Repaired Portion:
 - Limited warranty period for the repair of replacing with new scan-head: 12 months
 - Limited warranty period for the repair of replacing with new acoustic lens: 3 months
 - Limited warranty period for other repaired portion (such as replacing with new acoustic module): 6 months
 - BroadSound Corporation warrants that the repaired portion shall be free from defects in materials and workmanship for the warranty period after repair.
 - During the warranty period, at no cost or expense BroadSound Corporation would repair defective repaired portion that are not damaged by accident, neglect of handling, or neglect of usage.